Our Ref./Docket No: <u>CISCO-8280</u> Patent

### IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Inventor(s): Jones IV, et al.

Assignee: Cisco Technology, Inc.

Patent No: 7,342,872

Issue Date: March, 11, 2008

Application No.: 10/673,958

Filed: September 29, 2003

Title: DIFFERENTIAL OFDM USING MULTIPLE RECEIVER ANTENNAS

## REQUEST FOR CERTIFICATE OF CORRECTIONS

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Dear Commissioner:

The above patent contains significant error(s) as indicated on the attached Certificate of Correction form (submitted in duplicate).

X Such error(s) arose through the fault of the Patent and Trademark Office. It is requested that the certificate be issued at no cost to the applicant.

However, if it is determined that the error(s) arose through the fault of applicant(s), please note that such error is of clerical error or minor nature and occurred in good faith and therefore issuance of the certificate of Correction is respectfully requested. The Commissioner is authorized to charge Deposit Account No. 50-0292 any required fee. A duplicate of this request is attached.

Such error(s) specifically:

In column 3, line 60, kindly change " $7\pi/2$ " to  $-\pi/2$ --.

The undersigned requests being contacted at (510) 547-3378 if there are any questions or clarifications, or if there are any problems with issuance of the Certificate of Correction.

Respectfully Submitted,

March 24, 2008
Date

/Dov Rosenfeld/ #38687
Dov Rosenfeld, Reg. No. 38687
Agent of Record.

Address for correspondence:

Dov Rosenfeld 5507 College Avenue, Suite 2, Oakland, CA 94618

Tel.(510) 547-3378; Fax: (510) 291-2985

PATENT NO: <u>7,342,872</u>

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control purposer.

(Also Form PTO-1050)

# UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

SERVINION VIE SI SON RESTIGIV			
DAT	ENT NO:7,342,872 ED : March 11, 2008 ENTOR(S) : Jones IV, et al.	PAGE <u>1</u> of <u>1</u>	
Patent are he	It is certified that an error appears in the above-identified patent and that said Letters ereby corrected as shown below:		
	In column 3, line 60, kindly change " $7\pi/2$ " to $-\pi/2$		

Our Ref./Docket No: <u>CISCO-8280</u> Patent

### IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Inventor(s): Jones IV, et al.

Assignee: Cisco Technology, Inc.

Patent No: 7,342,872

Issue Date: March, 11, 2008

Application No.: 10/673,958

Filed: September 29, 2003

Title: DIFFERENTIAL OFDM USING MULTIPLE RECEIVER ANTENNAS

## REQUEST FOR CERTIFICATE OF CORRECTIONS

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Dear Commissioner:

The above patent contains significant error(s) as indicated on the attached Certificate of Correction form (submitted in duplicate).

X Such error(s) arose through the fault of the Patent and Trademark Office. It is requested that the certificate be issued at no cost to the applicant.

However, if it is determined that the error(s) arose through the fault of applicant(s), please note that such error is of clerical error or minor nature and occurred in good faith and therefore issuance of the certificate of Correction is respectfully requested. The Commissioner is authorized to charge Deposit Account No. 50-0292 any required fee. A duplicate of this request is attached.

Such error(s) specifically:

In column 3, line 60, kindly change " $7\pi/2$ " to  $-\pi/2$ --.

The undersigned requests being contacted at (510) 547-3378 if there are any questions or clarifications, or if there are any problems with issuance of the Certificate of Correction.

Respectfully Submitted,

March 24, 2008
Date

/Dov Rosenfeld/ #38687
Dov Rosenfeld, Reg. No. 38687
Agent of Record.

Address for correspondence:

Dov Rosenfeld 5507 College Avenue, Suite 2, Oakland, CA 94618

Tel.(510) 547-3378; Fax: (510) 291-2985

PATENT NO: <u>7,342,872</u>

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control purposer.

(Also Form PTO-1050)

# UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

SERVINION VIE SI SON RESTIGIV			
DAT	ENT NO:7,342,872 ED : March 11, 2008 ENTOR(S) : Jones IV, et al.	PAGE <u>1</u> of <u>1</u>	
Patent are he	It is certified that an error appears in the above-identified patent and that said Letters ereby corrected as shown below:		
	In column 3, line 60, kindly change " $7\pi/2$ " to $-\pi/2$		